CORNER RECORD

Agency Index

BK 23, PG 45

Document Number 20200089 Placer City of Rocklin County of California Brief Legal Description Centerline Sweetwater Dr., Antelope Oaks Unit No. 2, Bk. N of Maps, Pg. 40 **COORDINATES (Optional) CORNER TYPE** Se 18 Government Corner Control Elevation Meander Property Units Metric U.S. Survey Foot Rancho Other **Horizontal Datum** X Epoch Date Zone Date of Survey October 16, 2020 Vertical Datum Complies with Public Resources Code §§8801-8819 T. 11 N., R. 7 E., M.D.B. & M. Complies with Public Resources Code §§8890-8902 PLS Act Ref.: X 8771 8765(d) 8773 Other: Left as found **Pre-Construction** Established Rebuilt Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction ころとまる Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): Found railroad spike with punch at the centerline angle point and at subdivision boundary, Sweetwater Drive, as shown on Antelope Oaks Unit No. 2, Bk. N of Maps, Pg. 40 that could be damaged or destroyed by a proposed paving project. Monuments were referenced as shown on page 2 of 2. The purpose of this Corner Record is to preserve the location of the monuments prior to construction. No RECORUS attempt was made to determine the relationship between the monuments and boundary lines. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on January 14, 2021 Exp. 12-31-2022 P.L.S. or R.C.E. No. *P.L.S. 5914* Signed FOF CALL **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received and examined and filed P.L.S. or R.C.E. No. 8373 Signed Title

County Survéyor's Comment

